<u>PNWGFA Maintenance & Safety Workshop – DRAFT Agenda</u>

Day 1:

8:00–8:30 am	Introductions / orientation / expectations
8:30–9:15 am	Safety Training: HOT Work
9:15–10:00 am	Safety Training: Contractor Control
10:00–10:15 am	Break
10:15–10:45 am	Consequences of a Lapse in Safety (4 real life examples)
10:45–11:15 am	Grain Handling Equipment
11:15–12:00 pm	Session 1: General Plant Maintenance
12:00–1:00 pm	Lunch
1:00-2:00 pm	Session 2: Legs
2:00-3:00 pm	Session 3: Buckets / Belts / Splices
3:00-3:15 pm	Break
3:15-4:15 pm	Session 4: Belt Conveyors
4:15–5:00 pm	Wrap up Roundtable / Discussion
	<u>Day 2:</u>
8:00–8:30 am	Review / Todays expectations
0.00.000	
8:30–9:00 am	Session 5: Screw Conveyors
9:00–9:30 am	<u>Session 5</u> : Screw Conveyors <u>Session 6</u> : Chain Conveyors
	· · · · · · · · · · · · · · · · · · ·
9:00–9:30 am	Session 6: Chain Conveyors
9:00–9:30 am 9:30–9:45 am	Session 6: Chain Conveyors Break
9:00–9:30 am 9:30–9:45 am 9:45–10:15 am	Session 6: Chain Conveyors Break Session 6: Spouting / Distributors / Relining
9:00–9:30 am 9:30–9:45 am 9:45–10:15 am 10:15–12:00 pm	Session 6: Chain Conveyors Break Session 6: Spouting / Distributors / Relining Session 7: Bearings
9:00–9:30 am 9:30–9:45 am 9:45–10:15 am 10:15–12:00 pm 12:00–1:00 pm	Session 6: Chain Conveyors Break Session 6: Spouting / Distributors / Relining Session 7: Bearings Lunch
9:00–9:30 am 9:30–9:45 am 9:45–10:15 am 10:15–12:00 pm 12:00–1:00 pm 1:00–2:00 pm	Session 6: Chain Conveyors Break Session 6: Spouting / Distributors / Relining Session 7: Bearings Lunch Session 8: Motors / Drives / Gearboxes
9:00–9:30 am 9:30–9:45 am 9:45–10:15 am 10:15–12:00 pm 12:00–1:00 pm 1:00–2:00 pm 2:00–2:30 pm	Session 6: Chain Conveyors Break Session 6: Spouting / Distributors / Relining Session 7: Bearings Lunch Session 8: Motors / Drives / Gearboxes Session 9: Dust Systems
9:00–9:30 am 9:30–9:45 am 9:45–10:15 am 10:15–12:00 pm 12:00–1:00 pm 1:00–2:00 pm 2:00–2:30 pm 2:30–2:45 pm	Session 6: Chain Conveyors Break Session 6: Spouting / Distributors / Relining Session 7: Bearings Lunch Session 8: Motors / Drives / Gearboxes Session 9: Dust Systems Break
9:00–9:30 am 9:30–9:45 am 9:45–10:15 am 10:15–12:00 pm 12:00–1:00 pm 1:00–2:00 pm 2:00–2:30 pm 2:30–2:45 pm 2:45–3:30 pm	Session 6: Chain Conveyors Break Session 6: Spouting / Distributors / Relining Session 7: Bearings Lunch Session 8: Motors / Drives / Gearboxes Session 9: Dust Systems Break Session 10: Grain Dryers